

Milling | Endmills | Cutting conditions

Vibration control

A diagram showing a periodic surface profile. The profile consists of a series of rounded peaks and valleys. The vertical distance from the mean line to the peak is labeled ap . The horizontal distance between two consecutive peaks is labeled pf .